

Zinc Spray

Zinc coating spray for anti-corrosion protection of metal parts

AER2506

PRODUCT DESCRIPTION

It is used for coating, priming and retouching on body parts. It is widely used in agricultural machinery, trailers, silos, greenhouses, construction machinery, steel structures, etc., mostly in the field. Zinc spray is extremely durable and flexible. It protects active metal parts and completes electrochemical processes within itself. It provides active protection against corrosion.

FEATURES

- Long-lasting zinc shield
- Active rust defense
- Flexible, durable coating
- Primer coating & touch-up
- Aerosol can
- Full-cover cap

DIRECTIONS FOR USE

1. Shake & prepare — Shake well and make sure the surface is clean and dry.
2. Spray from 10-20 cm — Apply a thin, even coat across the surface.
3. Allow to dry — Wait until the coating is completely dry between coats.
4. Apply 8 hours before — For optimal protection, apply at least 8 hours before exposure.

PHYSICAL AND CHEMICAL PROPERTIES

Physical state	Aerosol. Active substance: liquid.
Colour	Grey (zinc)
Odour	Characteristic (solvent)
Density	≈ 0.90 g/cm³ (liquid content)
pH	Not applicable (non-aqueous)
Solubility in water	Insoluble

PACKAGING

Product Code	Pack Size	Units per Case	Barcode (EAN-13)
AER2506	400 ml	24	—

STORAGE

Pressurised container: protect from sunlight and do not expose to temperatures above 50 °C. Do not pierce or burn, even after use. Store in a cool, well-ventilated place. The expiry date, production date and lot number are printed on the pack.

SAFETY INFORMATION



Signal word: Danger

- H222 – Extremely flammable aerosol.
- H229 – Pressurised container: May burst if heated.
- H315 – Causes skin irritation.
- H319 – Causes serious eye irritation.
- H410 – Very toxic to aquatic life with long lasting effects.
- P102 – Keep out of reach of children.
- P210 – Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
- P211 – Do not spray on an open flame or other ignition source.
- P251 – Do not pierce or burn, even after use.
- P410+P412 – Protect from sunlight. Do not expose to temperatures exceeding 50 °C.
- P273 – Avoid release to the environment.
- P280 – Wear protective gloves / eye protection / face protection.
- P305+P351+P338 – IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P391 – Collect spillage.
- P501 – Dispose of contents / container to an approved waste disposal facility.

The information in this sheet is based on our current knowledge and experience; users should test the product under their own conditions of use. For safety information, refer to the product Safety Data Sheet (SDS).